





#### QUALIFICATIONS PACK - OCCUPATIONAL STANDARDS FOR TELECOM INDUSTRY

# What are Occupational Standards(OS)?

- OS describe what individuals need to do, know and understand in order to carry out a particular job role or function
- performance
  standards that
  individuals must
  achieve when
  carrying out
  functions in the
  workplace,
  together with
  specifications of
  the underpinning
  knowledge and
  understanding

#### Contact Us:

2nd Floor, PLOT: 105,Sector - 44, GURGAON - 122003 T: 0124 - 4148029 E-mail: tssc@tsscindia.com



### Contents

1.	Introduction and Contacts1
2.	Qualifications Pack2
3.	Glossary of Key Terms3
4.	OS Units5
5.	Assessment Criteria25

#### Introduction

### Qualifications Pack- Handset Repair Engineer (Level II)

**SECTOR:** TELECOM

**SUB-SECTOR:** Handset

**OCCUPATION:** Customer Service

**REFERENCE ID:** TEL/Q2201

**ALIGNED TO:** NCO-2015/7422.0203

**Brief Job Description:** Handset repair engineer is responsible for performing handset repair including hardware and software components and testing the handset for adequacy post repair.

**Personal Attributes:** This job requires the individual to be analytical and be able to handle high pressure situations to successfully perform the assigned responsibilities. He should have basic written and oral communication skills and should be able to apply practical judgement to successfully perform the assigned responsibilities.





#### Qualifications Pack For Handset Repair Engineer (Level II)





		_
	C	2
	4	ī
	Č	
		5
٠	Ò	
	_	=

Qualifications Pack Code	TEL/Q2201		
Job Role	Handset Repair Engineer (Level II)		
Credits NSQF	TBD	Version number	1.0
Sector	Telecom	Drafted on	15/07/13
Sub-sector	Handset Segment	Last reviewed on	29/04/15
Occupation	Customer Service	Next review date	31/05/17
NSQC Clearance on	18/06/2015		

Job Role	Handset Repair Engineer (Level II)		
Role Description	Handset repair engineer(Level II) is responsible for performing handset repair including hardware and software components, testing the handset for adequacy post repair and maintaining inventory levels of the hardware components.		
NSQF level	4		
Minimum Educational Qualifications*  Maximum Educational Qualifications*	10+2 / ITI / Diploma / Certification in repairing services Bachelor in Technology (Electronics, Computer Science, IT and related field)		
	Trainings on Digital electronics, handset( general),		
Training	Operating system.		
Minimum Job Entry Age	18 Years		
Experience	Fresher (For Entrepreneur career) Minimum 2 years in handset repair (For Industry career)		
Applicable National Occupational Standards (NOS)	Click to open the below hyperlinks  Compulsory:  1. TEL/N2203 (Perform handset repair- hardware)  2. TEL/N2204 (Perform handset repair- software)  3. TEL/N2205 (Perform tablet repair- hardware & software)  Optional:  N.A.		
Performance Criteria	As described in the relevant OS units		



#### Qualifications Pack For Handset Repair Engineer (Level II)





Keywords /Terms	Description		
Sector	Sector is a conglomeration of different business operations having similar businesses and interests. It may also be defined as a distinct subset of the economy whose components share similar characteristics and interests.		
Sub-sector	Sub-sector is derived from a further breakdown based on the characteristics and interests of its components.		
Occupation	Occupation is a set of job roles, which perform similar/related set of functions in an industry.		
Function	Function is an activity necessary for achieving the key purpose of the sector, occupation, or area of work, which can be carried out by a person or a group of persons. Functions are identified through functional analysis and form the basis of OS.		
Job Role	Job role defines a unique set of functions that together form a unique employment opportunity in an organization.		
OS	OS specify the standards of performance an individual must achieve when carrying out a function in the workplace, together with the knowledge and understanding they need to meet that standard consistently. Occupational Standards are applicable both in the Indian and global contexts.		
Performance Criteria	Performance Criteria are statements that together specify the standard of performance required when carrying out a task.		
NOS	NOS are Occupational Standards which apply uniquely in the Indian context.		
Qualifications Pack Code	Qualifications Pack Code is a unique reference code that identifies a qualifications pack.		
Qualifications Pack	Qualifications Pack comprises the set of OS, together with the educational, training and other criteria required to perform a job role. A Qualifications Pack is assigned a unique qualification pack code.		
Unit Code	Unit Code is a unique identifier for an Occupational Standard, which is denoted by an 'N'.		
Unit Title	Unit Title gives a clear overall statement about what the incumbent should be able to do.		
Description	Description gives a short summary of the unit content. This would be helpful to anyone searching on a database to verify that this is the appropriate OS they are looking for.		
Knowledge and Understanding	Knowledge and Understanding are statements which together specify the technical, generic, professional and organizational specific knowledge that an individual needs in order to perform to the required standard.		
Organizational Context	Organizational Context includes the way the organization is structured and how it operates, including the extent of operative knowledge managers have of their relevant areas of responsibility.		
Technical Knowledge	Technical Knowledge is the specific knowledge needed to accomplish specific designated responsibilities.		
Core Skills or Generic Skills	Core Skills or Generic Skills are a group of skills that are key to learning and working in today's world. These skills are typically needed in any work environment. In the context of the OS, these include communication related skills that are applicable to most job roles.		




# Qualifications Pack For Handset Repair Engineer (Level II)





Acronyms

Keywords /Terms	Description
ESD	Electro Static Discharge
KPI	Key Performance Indicator
OHS	Organizational Health & Safety
RAM	Random Access Memory
SHE	Safety, Health & Environment
SLA	Service Level Agreement



Back to top...










# National Occupational Standard



### **Overview**

This unit is about carrying out repair of handset equipment and related components.









National Occupational Standard

#### Perform handset repair - hardware

Unit Code	TEL/N2203		
Unit Title (Task)	Perform handset repair -hardware		
Description	This unit is about carrying out repair activities related to handset hardware		
Scope	<ul> <li>This unit/task covers the following:</li> <li>Undertake fault diagnosis</li> <li>Get appropriate spares from internal store</li> <li>Perform handset hardware related repair activities(handset equipment, associated components etc)</li> <li>Test handset post repair activity to ensure optimal performance</li> <li>Report and document the status at the end of repair activity</li> </ul>		
Performance Criteria (F	PC) w.r.t. the Scope		
Element	Performance Criteria		
Obtain handsets from customer/ relevant teams	PC1. ensure faulty handsets are received from the customer facing team PC2. obtain/ note fault details as mentioned by the customer facing team and other handset specifications PC3. obtain the committed repair timelines (SLAs) PC4. prioritize repair activities as per guidelines		
Arrange for tools and spares	To be competent, the user/individual on the job must be able to:  PC1. ensure clean, neat, dust free and organized working environment PC2. determine components required based on fault diagnosis PC3. obtain materials required( such as components, equipments, testing devices and other inventory) as per organizational procedures PC4. ensure that tools, equipments and testing devices are in proper working condition and caliberated PC5. ensure compliance with lead free soldering techniques		
Undertake Handset repair activities	To be competent, the user/individual on the job must be able to:  PC1. refer the company (handset manufacturer) specific technical database to identify root cause of handset fault and to determine rectification options  PC2. isolate the cause of fault by conducting appropriate diagnostic test, in case details are not available  PC3. determine the options to rectify the fault and confirm with supervisors, if required		









#### TEL/N2203 Perform handset repair - hardware

203	Perform handset repair - hardware
	PC4. dismantle handset/components as per organizational guidelines/procedures
	PC5. ensure rectification of handset fault within the SLAs
	PC6. ensure timely escalation of emergency/ unresolved issues according to
	established procedures
	PC7. ensure all repairs conform to the quality targets in terms of bounce and repeat
	repair percentages, first time fix etc
	To be competent, the user/individual on the job must be able to:
	PC1. assess test equipments are appropriately calibrated
	PC2. confirm effectiveness of the repair process, by utilizing appropriate test
Test effectiveness &	equipments as per standard test processes
close activity	PC3. ensure that fault has been rectified without any collateral damage to handset
close activity	· · · · · ·
	PC4. handover repaired handset to appropriate authority
	PC5. ensure completion of administrative jobs like site clearance, return of test
	equipments
	To be competent, the user/individual on the job must be able to:
	PC1. pass through ESD test before entering the facility
Cofet and to make	PC2. ensure that protection equipments like ESD equipments, anti-static bands,
Safety requirements	clothes and gloves are appropriately used as required
(Equipment & Self)	PC3. ensure compliance with site risk control, OHS, environmental and quality
	requirements as per company's norms
	PC4. ensure escalation of safety incidents to relevant authorities as per guidelines
	To be competent, the user/individual on the job must be able to:
	PC1. ensure that handset inventory in hand for repairs is tracked and accounted for
	appropriately as per company procedures
Report & Record	PC2. ensure record sheets are completed accurately, as per company guidelines
	PC3. ensure all relevant parties (including supervisors, customer teams) are notified
	of the completion of repair activity
	PC4. retain documents for specific period of time, as per company procedure
Knowledge and Unders	standing (K)
	The user/individual on the job needs to know and understand:
A. Organizational	
Context	KA1. risk and impact of not following defined procedures/work instructions
(Knowledge of the	KA2. escalation matrix for reporting identified incidents, troubles and/ or
company /	emergencies e.g. system failures ,fire and power failures
organization and	KA3. applicable Key Performance Indicators (KPIs) and Service Level Agreements
its processes)	(SLAs) including production rate and bounce rate (external and internal)
	KA4. types of documentation in organization and importance of the same
	KA5. process for obtaining sign-off post completion of the maintenance activities
	Figure 10. Contaming 5.0. on post completion of the manifestance detraited









#### TEL/N2203 Perform handset repair - hardware

2 <u>03</u>	Perform handset repair - hardware
	KA6. knowledge of spare management and repair & return process for faulty
	components
	KA7. SHE and OHS guidelines and regulations as per company's norms
	KA8. protection equipments (anti-static wrist bands, shoes, dress, packaging, and
	other appropriate insulations ) that are required to be used
	KA9. first aid requirements in case of electrical shocks, cuts and other common
	injuries
	The user/individual on the job needs to know and understand:
	KB1. functionality and features/working of handsets
	KB2. handset specific operating system and user interface
	KB3. functionality of hardware components in a handset like chipsets, processor,
	screen, touchpad etc.
B. Technical	KB4. have basic knowledge of electronic components in a handset
Knowledge	KB5. procedure to dismantle and assemble handset and handset components
	KB6. range of tools and testing equipment (multimeters, frequency generators etc)
	available and their functionality
	KB7. ESD hazards and their effect on electronic components
	KB8. range of handset related problems and their possible solutions
	KB9. standard fault-finding (troubleshooting) techniques
	g (* * * * * * * * * * * * * * * * * * *
Skills (S)	
	Reading skills
	The user/ individual on the job needs to know and understand how to:
	SA1. read and understand technical manuals, work orders and reports
	SA2. read and understand organizational health and safety instructions
	Writing Skills
	The user/ individual on the job needs to know and understand how to:
	SA3. fill up record sheets clearly, concisely and accurately as per company
A. Core Skills/	procedures
Generic Skills	
Concerts Same	Communication Skills
	The user/ individual on the job needs to know and understand how to:
	SA4. clearly communicate relevant information to supervisors
	SA5. respond appropriately to queries
	SA6. communicate with customer/customer facing teams to understand handset
	performance issues
	SA7. communicate in the local language
	SA8. convey proposed solution to the customers
	SA8. convey proposed solution to the customers









#### TEL/N2203 Perform handset repair - hardware

03	Perform handset repair - hardware
	Time Management Skills
	The user/individual on the job needs to know and understand how to:
	SA9. prioritize and execute tasks in a high-pressure environment
	SA10. use and maintain resources efficiently and effectively
	Analytical Skills
	The user/ individual on the job needs to know and understand how to:
	SA11. analyse (and understand) customer complaints
	SA12. interpret reports, readings and numerical data
	SA13. keep up to date with new technology and performance issues
	Other Skills
	The user/individual on the job needs to know and understand how to:
	SA14. create and maintain effective working relationships and team environment through collaboration
	SA15. take initiatives and progressively assume increased responsibilities
	SA16. share knowledge with other team members and colleagues
	Equipment operating Skills
B. Professional Skills	The user/individual on the job needs to know and understand how to:  SB1. use and access all handset features and applications  SB2. take data backup  SB3. operate handset testing equipments including test jigs, frequency generators
	etc
	SB4. connect hadset PCB to PC/test equipment for diagnostics SB5. initialize PC based diagnostic tools
	363. Illitialize PC based diagnostic tools
	Handset repairing skills
	The user/individual on the job needs to know and understand how to:
	SB6. undertake fault diagnostic
	SB7. interpret test results to identify and localize faults
	SB8. utilize appropriate mechanisms and tools to rectify the faults
	SB9. utilize appropriate communication channels to escalate unresolved problems
	SB10. test handset to confirm resolve of the reported fault
	Handset/Component Handling skills
	The user/individual on the job needs to know and understand how to:
	SB11. safely dismantle/assemble handset using the right tools
	SB12. safely connectorise the handset to PC for software transfer
	SB13. safe remove/replace components using right tools










203	Perform nandset repair - nardware
	SB14. compliance to ESD protection measures
	Toubleshooting Skills
	The user/individual on the job needs to know and understand how to:
	SB15. how to approach a defect
	SB16. make use of standard OEM specified troubleshooting steps
	SB17. Interpret intermediate results and progress fault rectification accordingly
	SB18. utilize appropriate tools to rectify faults











#### Perform handset repair - hardware

# **NOS Version Control:**

NOS Code	TEL/N2203		
Credits NSQF	TBD	Version number	1.0
Industry	Telecom	Drafted on	15/07/13
Industry Sub-sector	Handset Segment	Last reviewed on	29/04/15
		Next review date	31/05/17



Back to QP












# National Occupational Standard



## **Overview**

This unit is about carrying out fault rectification related to handset related software.

National Occupational Standard







204	Perform Handset Repair- Software
Unit Code	TEL/N2204
Unit Title (Task)	Perform handset repair – software
Description	This unit is about carrying out fault rectification related to handset software
Scope	This unit/task covers the following:  Undertake fault diagnosis  Ensure availability of correct software/software version  Perform software uploading/upgrade  Test handset post repair to ensure optimal performance  Report and document the status at the end of repair activity
Performance Crite	ria (PC) w.r.t. the Scope
Element	Performance Criteria
	To be competent, the user/individual on the job must be able to:

	Ensure availability of correct software/software version
	Perform software uploading/upgrade
	Test handset post repair to ensure optimal performance
	Report and document the status at the end of repair activity
Performance Criteria (F	PC) w.r.t. the Scope
Element	Performance Criteria
Obtain handsets from customer/ relevant teams	PC1. ensure faulty handsets are received from customer facing team PC2. obtain/ note fault details as mentioned by the customer facing team and other handset specifications PC1. obtain the committed repair timelines (SLAs) PC2. prioritize repair activities as per guidelines  To be competent, the user/individual on the job must be able to:
Determine change requirement	<ul> <li>PC1. undertake fault diagnosis on software components</li> <li>PC2. interpret results and isolate fault</li> <li>PC3. estimate repair timelines</li> <li>PC4. refer the company (handset manufacturer) specific technical database for optimal rectification options</li> <li>PC5. check availability of correct software versions/modules</li> </ul>
Arrange for related software, tools and spares	PC1. ensure clean, dust free and organized working environment PC2. ensure availability of connectors/cables PC3. obtain and ensure all tools are available and diagnostic equipment operational PC4. obtain software required as per organizational procedures PC5. ensure that the software versions are current and ready to use
Undertake repair activities	To be competent, the user/individual on the job must be able to:  PC1. carry out necessary software fault rectification ( correction/Upgradation, software replacement)









#### TEL/N2204 Perform Handset Repair- Software

204	Perform Handset Repair- Software
	PC2. ensure rectification of handset fault within the SLAs
	PC3. check handset performance to ascertain fault has been rectified
	PC4. ensure timely escalation of emergency/ unresolved issues according to
	established procedures
	PC5. ensure all repairs conform to the quality targets
	To be competent, the user/individual on the job must be able to:
	PC1. confirm effectiveness of the repair process, by testing the handset utilizing
	appropriate software jigs and standard test processes
T	PC2. take appropriate action to rectify any deficiencies post testing
Test effectiveness &	PC3. ensure that fault has been rectified without any consequal damage
close activity	PC4. handover repaired handset to QA team
	·
	PC5. ensure completion of administrative jobs like site clearance, return of test
	equipments
	To be competent, the user/individual on the job must be able to:
	To be competent, the aserymaniadal on the job must be able to.
	PC1. pass through ESD test before entering the facility
	PC2. ensure that protection equipments like anti-static bands, clothes and gloves
Safety requirements	
(Equipment & Self)	are appropriately used as required
	PC3. ensure compliance with site risk control, OHS, environmental and quality
	requirements as per company's norms
	PC4. ensure escalation of safety incidents to relevant authorities as per guidelines
	To be competent, the user/individual on the job must be able to:
	BC1 ansure that handset inventory in hand (for repairs) is tracked and associated
	PC1. ensure that handset inventory in hand (for repairs) is tracked and accounted
	for appropriately
Report & Record	PC2. ensure record sheets are completed accurately, as per company guidelines
Report & Record	PC3. ensure all concerned (supervisors, QA team, customer teams) are notified of
	the completion of repair activity
	PC4. retain documents for specific period of time, as per company procedure
Knowledge and Unders	standing (K)
A. Organizational	The user/individual on the job needs to know and understand:
Context	
(Knowledge of the	KA1. risk and impact of not following defined procedures/work instructions
company /	KA2. escalation matrix for reporting identified incidents, troubles and/ or
organization and	emergencies e.g. system failures ,fire and power failures
	KA3. applicable Key Performance Indicators (KPIs) and Service Level Agreements
its processes)	(SLAs) including production rate and bounce rate (external and internal)
	(SEAS) including production rate and bounce rate (external and internal)









#### TEL/N2204 Perform Handset Repair- Software

204	renorm nanuset kepan- software
	KA4. types of documentation in organization and importance of the same
	KA5. process for obtaining sign-off post completion of the maintenance activities
	KA6. knowledge of spare management and repair & return process for faulty
	equipments
	KA7. SHE and OHS guidelines and regulations as per company's norms
	KA8. protection equipments (anti-static wrist bands, shoes, dress, packaging, and
	other appropriate insulations ) that are required to be used
	KA9. first aid requirements in case of electrical shocks, cuts and other common
	injuries
	The user/individual on the job needs to know and understand:
	KB1. functionality, features and basic working of handsets
	KB2. basic computer knowledge to be able to run diagnostic tools
	KB3. handset specific operating system, their versions and user interface
B. Technical	KB4. functionality of hardware components, software applications, screen, touchpad
	etc.
Knowledge	KB5. functionality of various software jigs KB6.
	mobile technologies like GSM & CDMA KB7.
	default setting of handsets and networks
	KB8. range of handset software related problems and their possible solutions
	KB9. standard fault-finding (troubleshooting) techniques
	KB10. standard software testing techniques
	KB11. standard repairing process
Skills (S)	
	Reading skills
	The user/ individual on the job needs to know and understand how to:
	SA1. read and understand technical manuals, work orders and reports
	SA2. read and understand organizational health and safety instructions
	State Tead and anaerstand organizational nearth and surety more actions
	Writing Skills
	The user/ individual on the job needs to know and understand how to:
	SA1. fill up record sheets clearly, concisely and accurately as per company
A. Core Skills/	procedures
Generic Skills	procedures
	Communication Skills
	The user/ individual on the job needs to know and understand how to:
	SA2. clearly communicate relevant information to supervisors
	SA3. respond appropriately to any queries
	SA4. communicate with customer/customer facing teams to understand handset
	performance issues
	SA5. communicate in the local language
	SA6. convey proposed solution to the customers
	I JAO. CONVEY PROPOSED SOLUTION TO THE CUSTOMES









#### **Perform Handset Repair- Software**

04	Perform Handset Repair- Software
	Time Management Skills
	The user/individual on the job needs to know and understand how to:
	SA7. prioritize and execute tasks in a high-pressure environment
	SA8. use and maintain resources efficiently and effectively
	Analytical Skills
	The user/ individual on the job needs to know and understand how to:
	SA9. analyse (and understand) customer complaints
	SA10. interpret reports, readings and numerical data
	SA11. keep up to date with new technology
	Other Skills
	The user/individual on the job needs to know and understand how to:
	SA12. create and maintain effective working relationships and team environment
	through collaboration
	SA13. take initiatives and progressively assume increased responsibilities
	SA14. share knowledge with other team members and colleagues
	Software Skills
	The user/individual on the job needs to know and understand how to:
	SB1. identifying correct software version/modules
	SB2. ascertain correct and complete porting/update of software in the handset
	SB3. execute basic software commands for data transfer
	SB4. data backup prior attempting repairs
	SB5. initialize PC based diagnostic tools
	Handset repairing skills
	The user/individual on the job needs to know and understand how to:
B. Professional Skills	SB6. interpret diagnostic test results to identify and localize faults
	SB7. connect up handset to PC using connectors/cables
	SB8. undertake corrective repairs by software porting/updates
	SB9. undertake checks to confirm that the problem is resolved
	SB10. utilize appropriate communication channels to escalate unresolved problems
	to relevant personnel
	Toubleshooting Skills
	The user/individual on the job needs to know and understand how to:
	SB1. how to approach a defect
	SB2. make use of standard OEM specified troubleshooting steps
	SB3. interpret intermediate results and progress fault rectification accordingly
	SB4. utilize appropriate tools to rectify faults
	<u>'</u>










#### TEL/N2204 Perform Handset Repair- Software

# **NOS Version Control**

NOS Code	TEL/N2204		
Credits NSQF	TBD	Version number	1.0
Industry	Telecom	Drafted on	15/07/13
Industry Sub-sector	Handset Segment	Last reviewed on	29/04/15
		Next review date	31/05/17



Back to QP










TEL/N2205 Perform Tablet Repair – Hardware & Software

# National Occupational Standard



## Ov ervi ew

This unit is about carrying out hardware & software repair of tablet PCs.



# National Occupational Standards





TEL/N2205

#### Perform Tablet Repair - Hardware & Software

Unit Code	TEL/N2205
Unit Title (Task)	Tablet Repair – Hardware & Software
Description	This unit is about carrying out repair activities related to tablet hardware & software.
Scope	This unit/task covers the following:
	<ul> <li>Undertake fault diagnosis</li> <li>Identify hardware components to be repaired/replaced</li> <li>Identify software components to be formatted/reloaded</li> <li>Perform tablet hardware &amp; software related repair activities</li> <li>Test tablet post repair activity to ensure optimal performance</li> <li>Report and document the status at the end of repair activity</li> </ul>

#### Performance Criteria (PC) w.r.t. the Scope

Element	Performance Criteria	
Obtain tablets from customer/relevant teams	PC1. ensure faulty tablets are received from the customer facing team PC2. obtain/ note fault details as mentioned by the customer facing team and other tablet specifications PC3. obtain the committed repair timelines (SLAs) PC4. prioritize repair activities as per guidelines	
Arrange for tools and spares	To be competent, the user/individual on the job must be able to:  PC1. ensure clean, neat, dust free and organized working environment PC2. determine hardware components & software required based on fault diagnosis PC3. obtain hardware & software required( such as components, OS, Applications, testing devices and other inventory) as per organizational procedures PC4. ensure that tools, equipment and testing devices are in proper working condition and calibrated PC5. ensure compliance with lead free soldering techniques	
Undertake tablet repair activities	To be competent, the user/individual on the job must be able to:  PC1. refer the company (tablet manufacturer) specific technical database to identify root cause of tablet fault and to determine rectification options  PC2. isolate the cause of fault by conducting appropriate hardware/software diagnostic test  PC3. determine the options to rectify the fault and confirm with supervisors, if required	



# National Occupational Standards





TEL/N2205

	PC4. dismantle tablet as per product/manufacturer guidelines PC5. ensure rectification of tablet fault within the SLAs PC6. ensure timely escalation of emergency/ unresolved issues according to established procedures PC7. ensure all repairs conform to the quality targets in terms of bounce and repeat repair percentages, first time fix etc.	
Test effectiveness & close activity	PC1. assess test equipment is appropriately calibrated PC2. confirm effectiveness of the repair process, by utilizing appropriate test equipment as per standard test processes PC3. ensure that fault has been rectified without any collateral damage to tablet PC4. handover repaired tablet to appropriate authority PC5. ensure completion of administrative jobs like site clearance, return of test equipment	
Safety requirements (Equipment & Self)	To be competent, the user/individual on the job must be able to:  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipment like ESD equipment, anti-static bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms PC4. ensure escalation of safety incidents to relevant authorities as per guidelines	
Report & Record	To be competent, the user/individual on the job must be able to:  PC1. ensure that tablet inventory in hand for repairs is tracked and accounted for appropriately as per company procedures  PC2. ensure record sheets are completed accurately, as per company guidelines  PC3. ensure all relevant parties (including supervisors, customer teams) are notified of the completion of repair activity  PC4. retain documents for specific period of time, as per company procedure	
Knowledge and Unders	standing (K)	
A. Organizational Context (Knowledge of the company / organization and its processes)	<ul> <li>KA1. risk and impact of not following defined procedures/work instructions</li> <li>KA2. escalation matrix for reporting identified incidents, troubles and/ or emergencies e.g. system failures ,fire and power failures</li> <li>KA3. applicable Key Performance Indicators (KPIs) and Service Level Agreements (SLAs) including production rate and bounce rate (external and internal)</li> <li>KA4. types of documentation in organization and importance of the same</li> <li>KA5. process for obtaining sign-off post completion of the maintenance activities</li> <li>KA6. knowledge of spare management and repair &amp; return process for faulty components</li> <li>KA7. Knowledge of obtaining verified OS, patches and application software from correct organizational channel</li> <li>KA8. SHE and OHS guidelines and regulations as per company's norms</li> </ul>	



# National Occupational Standards





#### **TEL/N2205**

	KAO protection equipment (anti-static societ hands also a durant protection and
	KA9. protection equipment (anti-static wrist bands, shoes, dress, packaging, and other appropriate insulations ) that are required to be used
	KA10. first aid requirements in case of electrical shocks, cuts and other common injuries
	The user/individual on the job needs to know and understand:
	KB1. basic electronics
	KB2. functional differences between computer, laptop, smartphone, tablet, i-
	phone and similar devices
	KB3. types and peculiarities of OS in tablets
n Table tab	KB4. types and peculiarities of tablet user interface
B. Technical	KB5. basic details and features of Windows and Android OS
Knowledge	KB6. functionality of hardware components in a tablet like touchscreen, LCD
	screen, camera, speakers, PCB etc.
	KB7. procedure to dismantle and assemble tablet
	KB8. formatting and installing of OS
	KB9. drivers and application installation in tablets
	KB10. range of tools and testing equipment (multi-meter, oscilloscope etc.)
	available and their functionality
	KB11. ESD hazards and their effect on electronic components
	KB12. range of tablet related problems and their possible solutions
	KB13. standard fault-finding (troubleshooting) techniques
Skills (S)	
	Writing Skills
	The user/ individual on the job needs to know and understand how to:
	SA1. fill up record sheets clearly, concisely and accurately as per company
	procedures
	Reading Skills
	The user / individual on the ich usered to lineau and understand hourte.
	The user/individual on the job needs to know and understand how to:
A. Core Skills/	SA2. read and understand technical manuals, work orders and reports
Generic Skills	SA3. read and understand organizational health and safety instructions
	Oral Communication (Listening and Speaking skills)
	The user/individual on the job needs to know and understand how to:
	SA4. clearly communicate relevant information to supervisors
	SA5. respond appropriately to queries
	SA6. communicate with customer/customer facing teams to understand tablet
	SA7. performance issues
	·
	SA8. communicate in the local language SA9. convey proposed solution to the customers









	Time Management Skills
	The user/individual on the job needs to know and understand how to:  SA10. prioritize and execute tasks in a high-pressure environment
	SA11. use and maintain resources efficiently and effectively
	Analytical Skills
	The user/individual on the job needs to know and understand how to:
	SA12. analyze (and understand) customer complaints
	SA13. interpret reports, readings and numerical data
	SA14. keep up to date with new technology and performance issues
	Other Skills
	The user/individual on the job needs to know and understand how to:  SA15. create and maintain effective working relationships and team environment through collaboration  SA16. take initiatives and progressively assume increased responsibilities
	SA17. share knowledge with other team members and colleagues
	Equipment Operating Skills
	The user/individual on the job needs to know and understand how to: SB1. use and access all handset features and applications SB2. take data backup SB3. operate tablet testing equipment including test jigs, oscilloscope etc. SB4. connect tablet PCB to PC/test equipment for diagnostics SB5. initialize PC based diagnostic tools
	Tablet Repairing Skills
	The user/individual on the job needs to know and understand:
B. Professional Skills	SB6. undertake fault diagnostic
	SB7. identify OS and application versions SB8. interpret test results to identify and localize faults
	SB9. utilize appropriate mechanisms and tools to rectify the faults
	SB10. execute basic software commands for data transfer, updates
	SB11. utilize appropriate communication channels to escalate unresolved problems
	SB12. test tablet to confirm resolve of the reported fault
	Tablet Handling Skills
	The user/individual on the job needs to know and understand how to:
	SB13. safely dismantle/assemble tablet using the right tools
	SB14. safely connect the table to PC for software transfer and diagnostic
	SB15. safely remove/replace components using right tools SB16. compliance to ESD protection measures
	3510. compliance to L35 protection measures










Troubleshooting Skills
The user/individual on the job needs to know and understand how to:
SB17. how to approach a defect SB18. make use of standard OEM specified troubleshooting steps SB19. interpret intermediate results and progress fault rectification accordingly SB20. utilize appropriate tools to rectify faults












#### Perform Tablet Repair – Hardware & Software

# **NOS Version Control**

NOS Code	TEL/N2205		
Credits NSQF	TBD	Version number	1.0
Industry	Telecom	Drafted on	16/09/13
Industry Sub-sector	Handset Segment	Last reviewed on	29/04/15
		Next review date	31/05/17



Back to QP



#### Qualification Pack for Handset Repair Engineer L II





#### **CRITERIA FOR ASSESSMENT OF TRAINEES**

Job Role Handset Repair Engineer Level II

 Qualification Pack
 TEL/Q2201

 Sector Skill Council
 Telecom

#### **Guidelines for Assessment:**

- 1. Criteria for assessment for each Qualification Pack will be created by the Sector Skill Council. Each Performance Criteria (PC) will be assigned marks proportional to its importance in NOS. SSC will also lay down proportion of marks for Theory and Skills Practical for each PC.
- 2. The assessment for the theory part will be based on knowledge bank of questions created by the SSC.
- 3. Individual assessment agencies will create unique question papers for theory part for each candidate at each examination/training center (as per assessment criteria below)
- 4. To pass the Qualification Pack, every trainee should score a minimum of 40% in every NOS and 50% overall.
- 5. In case of successfully passing only certain number of NOS's, the trainee is eligible to take subsequent assessment on the balance NOS's to pass the Qualification Pack.

Assessment Outcome Assessment Criteria

				Marks	Allocation	
<b>NOS្បាំងេ</b> 203 (Perform handset repair -	Elements	Performance Criteria	Total Mark (200)	Out Of	Theory	Skills Practical
hardware)	Obtain handsets from customer/ relevant teams	PC1. ensure faulty handsets are received from the customer facing team PC2. obtain/ note fault details as mentioned by the customer facing team and other	100			
		handset specifications PC3. obtain the committed repair timelines (SLAs)		15	15	
		PC4. prioritize repair activities as per guidelines		5		5
	Arrange for tools and spares	PC1. ensure clean, neat, dust free and organized working environment PC2. determine components required based on fault diagnosis				
		PC3. obtain materials required( such as components, equipments, testing devices and other inventory) as per organizational procedures				

	PC4. ensure that tools, equipments and testing
	devices are in proper working condition and
	caliberated
	PC5. ensure compliance with lead free soldering
	techniques
	teeriniques
Undertake Handset	
	DC1 refer the service (bendest reconfecture)
repair activities	PC1. refer the company (handset manufacturer)
	specific technical database to identify root cause of
	handset fault and to determine rectification options
	PC2. isolate the cause of fault by conducting
	appropriate diagnostic test, in case details are not
	available
	PC3. determine the options to rectify the fault and
	confirm with supervisors, if required
	PC4. dismantie nandset/components as per
	organizational guidelines/procedures
	PC5. ensure rectification of handset fault within the
	SLAs
	PC6. ensure timely escalation of emergency/
	unresolved issues according to established
	procedures
	PC7. ensure all repairs conform to the quality targets
	in terms of bounce and repeat repair
	percentages, first time fix etc
Safety requirements	PC1. pass through ESD test before entering the
(Equipment & Self)	facility
(Equipment & Sen)	PC2. ensure that protection equipments like ESD
	equipments, anti-static bands, clothes and gloves are
	appropriately used as required
	PC3. ensure compliance with site risk control, OHS,
	environmental and quality requirements as per
	company's norms
	PC4. ensure escalation of safety incidents to relevant
	authorities as per guidelines
	additionates as per guidenites
Danasat O. Danasad	PC1. ensure that handset inventory in hand for
Report & Record	repairs is tracked and accounted for appropriately as
	per company procedures

15	15	
45		45
10	10	

		PC3. ensure all relevant parties (including supervisors, customer teams) are notified of the completion of repair activity PC4. retain documents for specific period of time, as per company procedure		10	10	
2. TEL/N2204 (Perform handset repair –	Obtain handsets from	PC1. ensure faulty handsets are received from	100Total	100	50	50
software)	customer/ relevant teams	customer facing team PC2. obtain/ note fault details as mentioned by the customer facing team and other handset specifications				
		PC3. obtain the committed repair timelines (SLAs)		10	10	
		PC4. prioritize repair activities as per guidelines		5	5	
	Determine change	PC1. undertake fault diagnosis on software				
	requirement	components				
		PC2. interpret results and isolate fault PC3. estimate repair timelines PC4. refer the company (handset manufacturer) specific technical database for optimal rectification options PC5. check availability of correct software versions/modules		15	7	8
	Arrange for related	PC1. ensure clean, dust free and organized working				
	software, tools and	environment				
	spares	PC2. ensure availability of connectors/cables PC3. obtain and ensure all tools are available and diagnostic equipment operational PC4 obtain software required as per organizational procedures PC5 ensure that the software versions are current and ready to use		10	10	
	Undertake repair					
	activities	PC1. carry out necessary software fault rectification (correction/Upgradation, software replacement)				
		PC2. ensure rectification of handset fault within the SLAs				

environmental and quality requirements as per  company's norms  PC4. ensure escalation of safety incidents to relevant	environmental and quality requirements as per company's norms	environmental and quality requirements as per company's norms	environmental and quality requirements as per company's norms	environmental and quality requirements as per			used as required	letatic hands, clothes, and gloves are appropriately.	PC2. ensure that protection equipments like anti-	(Equipment & Self) facility PC2. ensure that protection equipments like anti-	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 1:  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  Facility PC2. ensure that protection equipments like anti-		used as required			
					environmental and quality requirements as per	PC3. ensure compliance with site risk control, OHS,			PC2. ensure that protection equipments like anti- static bands, clothes and gloves are appropriately	(Equipment & Self)  facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately		PC3. ensure compliance with site risk control, OHS,			
PC4. ensure escalation of safety incluents to relevant	rc4. ensure escalation of safety incluents to relevant	TEL 4 POSITIE PSI ATATIONI DE SATETY DE COPONS DE TELEVANE ■	IDCA ansure assolution of safety incidents to relevant		company's norms	environmental and quality requirements as per		used as required PC3. ensure compliance with site risk control, OHS,	PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	facility  (Equipment & Self)  facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  Facility PC2. ensure that protection equipments like anti- static bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,		company's norms			
authorities as per guidelines	authorities as per guidelines	authorities as per guidelines	authorities as per guidelines	PC4. ensure escalation of safety incidents to relevant			environmental and quality requirements as per	used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	(Equipment & Self)  facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  Safety requirements  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per		PC4. ensure escalation of safety incidents to relevant	10	10	
authorities as per guidelines 10 10	authorities as per guidelines 10 10	authorities as per guidelines 10 10	authorities as per guidelines 10 10		PC4. ensure escalation of safety incidents to relevant	<del>company's norms</del>	environmental and quality requirements as per company's norms	used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	facility  (Equipment & Self)  facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  Fc1. pass through ESD test before entering the facility PC2. ensure that protection equipments like anti- static bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms		authorities as per guidelines	10	10	
Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  Fc2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  Fo2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  Fo2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required  PC3. ensure compliance with site risk control, OHS,	Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  Facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	Safety requirements PC1. pass through ESD test before entering the  (Equipment & Self) facility PC2. ensure that protection equipments like anti-	Safety requirements PC1. pass through ESD test before entering the	isite clearance, return or test equipments 15 3 12	I cita classanca raturn at tact aquinmants	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage		PC5. ensure completion of administrative jobs like			
PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the facility  (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like anti-	PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	PC5. ensure completion of administrative jobs like	PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any					
PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  Fc2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like anti-	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing		· I			
consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the  (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like anti-	consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any					
PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like anti-	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity testing the handset utilizing appropriate software jigs and standard test processes					
deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required  PC3. ensure compliance with site risk control, OHS,	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like anti-	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs					
PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  (Equipment & Self)  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required  PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the facility  PC2. ensure that protection equipments like anti-	PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by	close activity				
and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like Site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like Site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like anti-	and standard test processes  PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team  PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	unresolved issues according to established procedures  PC5. ensure all repairs conform to the quality targets  25 3 22	Test effectiveness &				
close activity  testing the handset utilizing appropriate software jigs  and standard test processes  PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like anti- static bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like anti- static bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  PC1. pass through ESD test before entering the (Equipment & Self)  PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	close activity  testing the handset utilizing appropriate software jigs and standard test processes  PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like anti-	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements  PC1. pass through ESD test before entering the	close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	close activity  testing the handset utilizing appropriate software jigs and standard test processes  PC2. take appropriate action to rectify any deficiencies post testing  PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	unresolved issues according to established		PC5. ensure all repairs conform to the quality targets	25	3	22
PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by  close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the (Equipment & Self)  FC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Fc2. ensure that protection equipments like anti-	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 22  Safety requirements PC1. pass through ESD test before entering the	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by  close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like			_			
procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per company's norms	procedures PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) Facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS, environmental and quality requirements as per	procedures PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  Fc1. pass through ESD test before entering the (Equipment & Self)  facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately used as required PC3. ensure compliance with site risk control, OHS,	procedures PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the (Equipment & Self) facility PC2. ensure that protection equipments like antistatic bands, clothes and gloves are appropriately	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements (Equipment & Self)  FC1. pass through ESD test before entering the (Equipment & Self)	procedures PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like site clearance, return of test equipments  15 3 12  Safety requirements PC1. pass through ESD test before entering the	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by  close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like	procedures  PC5. ensure all repairs conform to the quality targets PC1. confirm effectiveness of the repair process, by close activity  testing the handset utilizing appropriate software jigs and standard test processes PC2. take appropriate action to rectify any deficiencies post testing PC3. ensure that fault has been rectified without any consequal damage  PC4. handover repaired handset to QA team PC5. ensure completion of administrative jobs like			PC4. ensure timely escalation of emergency/			